


TASCAM MH-40B

TEAC Production Products

SCHEMATIC DIAGRAM



INSTRUCTIONS FOR SERVICE PERSONNEL

BEFORE RETURNING APPLIANCE TO THE CUSTOMER, MAKE LEAKAGE-CURRENT OR RESISTANCE MEASUREMENTS TO DETERMINE THAT EXPOSED PARTS ARE ACCEPTABLY INSULATED FROM THE SUPPLY CIRCUIT.

△ Parts marked with this sign must always be replaced with ic Refer to the appropriate parts l

